



International Carwash Association
Serving the Professional Car Care Industry

401 N. Michigan Avenue
Chicago, Illinois 60611-4267
P 312.321.5199
F 312.245.1085
e-mail: ica@smithbucklin.com
www.CarCareCentral.com

Karcher Dryer Systems Alert

Some car wash operators with Karcher automatic car wash dryer systems have experienced problems when the vehicle being serviced has add-on items (e.g. exterior mounted spare tires).

Karcher dryer systems are equipped with “photo eyes” that are used to map the shape of vehicles. This mapping allows the dryer to follow the surface of standard vehicles at a defined distance, but Karcher has identified some exceptional situations when vehicle contact, and thereby potential damage, can occur.

The [bulletin from Karcher](#) describes how you can determine if your dryer could contact vehicles incorrectly, and suggestions for modifying the dryer system. Car wash operators can also request free modification kits from Karcher. For more information, contact your distributor or Karcher directly.

Please [report any vehicle damage](#) occurring at your wash and share all [Vehicle Alerts](#) with your staff.

If you have any questions, please contact the International Carwash Association at <mailto:info@CarCareCentral.com>.

Joe Ward
Director of Engineering
International Carwash Association